C CONTRACTOR)	Deltona Fire Departn 1685 Providence Blv Deltona, FL 32725 Office (386) 575-690 www.deltonafl.gov	d. Di
Occupant Name:	Richard Milburn Aca Volusia	demy - Inspection Date:	9/4/2024 (Initial Insp. Date: 8/28/2024)
Address:	1200 Deltona Boulev	ard InspectionType:	Reinspection #1 (Consultation)
Suite:	52/56		
Structure Name: City:	Deltona	Inspected By:	Sam Schaller sschaller@deltonafl.gov
Insp. Result	Location	Code Set	Code
Deficiency - Clear	ed Suite 56	FL NFPA 01 2021 Chapter 14 Means of Egress	14.5.2.6.2* - Key-Operated Locks Not Maintained
	√ Cleared	on 9/4/2024	
	Inspector C Lock has be	omments: en removed from egress side of doo	or.
	Found mark	ction Comment- ed means of egress door locked ag Key was provided and door was un	ainst egress during school hours and while classroom locked on site.
		upon receipt: Remove the key-ope ks shall not be permitted on the egr	rated lock from the egress side of the door. Key ress side of door.
	Important no	te: Door is permitted to be locked to	o prevent unauthorized ingress, however, door can

Inspector Comments: Re-Inspection #1, no invoice fee applied.

Your inspection today revealed fire code deficiencies that require immediate attention and/or repair. A follow-up inspection will be conducted to verify code compliance. Failure to comply may result in further action.

Should you have any questions, please contact your Inspector. If you feel the need to speak with the supervisor, please contact Chief Shivers Fire Marshal at 386-575-6909 or sshivers@deltonafl.gov

Important Note:

Please note that you may be visited by a Deltona Fire Department engine crew. This is not to conduct an inspection but to conduct a pre-fire survey of your property to identify features critical to safe fire response.

Ref: 7931-8045